

ପା/ପୋ- ହିନ୍ଦୋଳରୋଡ଼
ଜିଲ୍ଲା- ଦେଙ୍କାନାଳ
ରାଜ୍ୟ- ଓଡ଼ିଶା
ପିନ୍ - ୭୫୯୦୧୯
ଇ-ମେଲ୍- ori-odapada@nic.in
ଦୂରଭାଷା- ୦୬୭୩୨-୨୫୬୦୩୫



ପଞ୍ଚାୟତ ସମିତି କାର୍ଯ୍ୟାଳୟ, ଓଡ଼ାପଡ଼ା
OFFICE OF THE PANCHAYAT SAMITI, ODAPADA

Letter No. 485 /Dt. 12.02.2019

At/Po. Hindol Road
Dist. Dhenkanal
State: Odisha
PIN:-759019
Mail ID:ori-odapada@nic.in
Ph.No.06732-256035

To

The Principal,
Brahmani Public School,
At- Kharagprasad, Dist- Dhenkanal

Sub:- Issue of Certificates Building Safety certificate , Health, Sanitation Certificate and Safe Drinking Water Certificate.

Sir,

As per your request the Asst. Engineer, Odapada Block has inspected the Building Safety, Health, Sanitation and Safe Drinking Water provided at your level and opined that

1. The School Building is located in a compact area.
2. The School Building is with all the infrastructure as per the provisions of National Building Code and National Disaster Management Authority.
3. Each Class Room have good ventilation system which allowed free flow of air in and out through attached skylights, windows and doors.
4. Each class room have two doors for in and out of the class.
5. Two staircases exist in the school building for the children.
6. Proper drinking water supplied for in and out of the class.
7. The building is properly surrounded by Boundary wall for protection of students and the gates remained closed during school hour.
8. First- Aid Box also available for primary treatment of the students.
9. The school building is every year coloured and maintenance carried out to upkeep in well condition.
10. The structural construction, lay outs, design & strength of the building as per standard norms.

This certificate is given for producing it before the appropriate authority.

Yours faithfully

Block Development Officer
ODAPADA



WE SERVE TO SAVE

OFFICE OF THE DEPUTY FIRE OFFICER
ANGUL CIRCLE, ANGUL

FORM-V
FIRE SAFETY CERTIFICATE

(See rule-13 (3) of the Odisha Fire Prevention and Fire Safety (Amendment) Rules, 2019)

File No-03A-2019 (Edu)

Certificate No.09/2019/AGL CRL

Dated.06.12.2019

This Certificate valid up to 05.12.2021

(Applied for renewal at least three months before expire)

Certified that Brahmani Public School, At-Kharagprasad, PS-Motangan, Dist-Dhenkanal consisting of total one block was inspected by officers of Odisha Fire Service on 27.11.2019 in presence of the Principal, Brahmani Public School and it has been found to comply with the Fire Prevention and Fire Safety requirements in accordance with Odisha Fire Prevention and Fire Safety (Amendment) Rules, 2019 and that is various floors are fit for occupancy or usage are noted hereunder against each subject to compliance to the conditions as prescribed herein below:-

1.	G to 1 st floor (01 Block)	-Usages-	Educational
----	---------------------------------------	----------	-------------

CONDITIONS:-

1. Fire prevention and fire safety measures and appliances, availability of water supplies and means of access thereto etc. provided in the building or premises, should be maintained by the occupier(s) in best repairs and efficient working condition at all times for use by the occupants or members of the Fire Service or both in the event of outbreak of fire.
2. The set-backs, driveways, entrance gate exists staircase corridors and escape ways should not be changed, obstructed or modified in any way.
3. The occupier(s) shall train all staff and occupants periodically to make them well conversant in use and operation of the Fire Prevention and Safety Measures.
4. Fire Drills/ rehearsals should be organized at least one in six months by involving local fire station.
5. Photocopies of this certificate should be framed and displayed at all conspicuous places in all lobbies/corridors in all floors of all towers/blocks building, premises.

(Chandra Mohan Routray)

Deputy Fire Officer
Angul Circle, Angul

Deputy Fire Officer
Angul Circle, Angul